




TOYOKAWA 1344-216 2026/01/18(018)05:48:37-05:52:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1351-211 2026/01/18(018)05:55:16-05:58:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1410-069 2026/01/18(018)06:14:33-06:17:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1414-03 2026/01/18(018)06:18:19-06:21:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1418-025 2026/01/18(018)06:22:08-06:25:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1423-177 2026/01/18(018)06:26:58-06:30:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2026/01/18(018)06:31:44-06:35:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1436-16 2026/01/18(018)06:40:25-06:43:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1453-10 2026/01/18(018)06:56:48-07:00:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1508-05 2026/01/18(018)07:11:41-07:15:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318


2026/01/18(018)07:20:40-07:24:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1523+03 2026/01/18(018)07:26:27-07:29:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1535+139 2026/01/18(018)07:38:07-07:41:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1545-12 2026/01/18(018)07:48:31-07:51:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1607+26 2026/01/18(018)08:09:33–08:12:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1623-228 2026/01/18(018)08:27:05-08:30:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1631-222 2026/01/18(018)08:35:35-08:39:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1638-025 2026/01/18(018)08:41:12-08:44:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1644-106 2026/01/18(018)08:48:07-08:51:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1650+004 2026/01/18(018)08:53:27-08:56:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2026/01/18(018)09:15:29-09:18:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1730-13 2026/01/18(018)09:33:31-09:36:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1748+031 2026/01/18(018)09:50:55–09:54:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1759+13 2026/01/18(018)10:01:48-10:05:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1819-096 2026/01/18(018)10:22:49-10:26:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1835+134 2026/01/18(018)10:37:32–10:40:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1858+171 2026/01/18(018)11:00:28–11:03:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1908-20 2026/01/18(018)11:11:14-11:14:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1915-121 2026/01/18(018)11:18:04-11:21:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1928-142 2026/01/18(018)11:31:46-11:35:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1938-15 2026/01/18(018)11:41:25-11:44:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2007+502 2026/01/18(018)12:08:36–12:12:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2014+358 2026/01/18(018)12:16:20-12:19:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C422 2026/01/18(018)12:46:57-12:50:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2105-072 2026/01/18(018)13:07:35-13:11:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2131+379 2026/01/18(018)13:33:20–13:36:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2135-209 2026/01/18(018)13:37:39-13:41:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2147+145 2026/01/18(018)13:49:58–13:53:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2156-043 2026/01/18(018)13:59:03-14:02:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2203-18 2026/01/18(018)14:05:52-14:09:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2210+016 2026/01/18(018)14:12:14–14:15:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2218+395 2026/01/18(018)14:19:54–14:23:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C446


2026/01/18(018)14:25:23-14:28:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2229-093 2026/01/18(018)14:32:07-14:35:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2235+511 2026/01/18(018)14:36:39–14:40:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2239+333 2026/01/18(018)14:40:52-14:44:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2243+394 2026/01/18(018)14:45:09–14:48:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C454.3 2026/01/18(018)14:53:23–14:56:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2259+481 2026/01/18(018)15:01:05–15:04:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C456


2026/01/18(018)15:11:54–15:15:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C459 2026/01/18(018)15:15:59-15:19:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2318-16 2026/01/18(018)15:20:27-15:23:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2325+269 2026/01/18(018)15:27:19–15:30:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2344+09 2026/01/18(018)15:45:58–15:49:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2347-02 2026/01/18(018)15:49:44-15:53:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2354+14 2026/01/18(018)15:56:38-16:00:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C2


2026/01/18(018)16:05:40–16:09:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0011+344 2026/01/18(018)16:13:02-16:16:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0019-00 2026/01/18(018)16:21:39-16:25:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C12


2026/01/18(018)16:31:53–16:35:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0044-056 2026/01/18(018)16:45:55-16:49:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C26


2026/01/18(018)16:53:16–16:56:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0056-00 2026/01/18(018)16:58:15-17:01:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0106+01 2026/01/18(018)17:07:57-17:11:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0115-01 2026/01/18(018)17:17:20-17:20:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0128+03 2026/01/18(018)17:30:19–17:33:45JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0156-144 2026/01/18(018)17:57:38-18:01:04JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

