




TOYOKAWA 1437-247 2026/01/29(029)05:58:22-06:01:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1441-183 2026/01/29(029)06:02:05-06:05:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1445-161 2026/01/29(029)06:05:56-06:09:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1453-10 2026/01/29(029)06:13:33-06:16:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1458-197 2026/01/29(029)06:18:57-06:22:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1502-001 2026/01/29(029)06:23:05-06:26:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1508-05 2026/01/29(029)06:28:26-06:31:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1518+04 2026/01/29(029)06:38:40-06:42:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1523+03 2026/01/29(029)06:43:12-06:46:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1535+139 2026/01/29(029)06:54:52-06:58:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545-12 2026/01/29(029)07:05:16-07:08:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2026/01/29(029)07:26:18-07:29:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1623-228 2026/01/29(029)07:43:50-07:47:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2026/01/29(029)07:52:20-07:55:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2026/01/29(029)07:57:57-08:01:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2026/01/29(029)08:04:52-08:08:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1650+004 2026/01/29(029)08:10:12-08:13:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1656+053 2026/01/29(029)08:15:44-08:19:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2026/01/29(029)08:32:14-08:35:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1730-13 2026/01/29(029)08:50:16-08:53:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2026/01/29(029)09:07:40-09:11:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2026/01/29(029)09:18:33-09:21:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1819-096 2026/01/29(029)09:39:34-09:43:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1835+134 2026/01/29(029)09:54:17-09:57:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1858+171 2026/01/29(029)10:17:13-10:20:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1908-20 2026/01/29(029)10:27:59-10:31:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1915-121 2026/01/29(029)10:34:49-10:38:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1928-142 2026/01/29(029)10:48:31-10:51:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1938-15 2026/01/29(029)10:58:10-11:01:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2007+502 2026/01/29(029)11:25:21-11:28:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2014+358 2026/01/29(029)11:33:05-11:36:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C422 2026/01/29(029)12:03:43-12:07:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2026/01/29(029)12:24:20-12:27:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2131+379 2026/01/29(029)12:50:05-12:53:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2135-209 2026/01/29(029)12:54:24-12:57:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2147+145 2026/01/29(029)13:06:43-13:10:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2156-043 2026/01/29(029)13:15:48-13:19:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2203-18 2026/01/29(029)13:22:37-13:26:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2210+016 2026/01/29(029)13:28:59-13:32:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2218+395 2026/01/29(029)13:36:39-13:40:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C446

2026/01/29(029)13:42:09-13:45:35JST


12746+/- 2276




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2229-093 2026/01/29(029)13:48:52-13:52:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2235+511 2026/01/29(029)13:53:24-13:56:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2239+333 2026/01/29(029)13:57:37-14:01:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2243+394 2026/01/29(029)14:01:54-14:05:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C454.3 2026/01/29(029)14:10:08-14:13:34JST


14965+/- 408




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2259+481 2026/01/29(029)14:17:50-14:21:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C456 2026/01/29(029)14:28:39-14:32:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C459 2026/01/29(029)14:32:44-14:36:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2318-16 2026/01/29(029)14:37:12-14:40:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2325+269 2026/01/29(029)14:44:04-14:47:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2344+09 2026/01/29(029)15:02:43-15:06:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2347-02 2026/01/29(029)15:06:29-15:09:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2354+14 2026/01/29(029)15:13:23-15:16:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C2


2026/01/29(029)15:22:25-15:25:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0011+344 2026/01/29(029)15:29:47-15:33:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0019-00 2026/01/29(029)15:38:24-15:41:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C12

2026/01/29(029)15:48:38-15:52:04JST


16170+/- 3461




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0038+328 2026/01/29(029)15:56:56-16:00:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0044-056 2026/01/29(029)16:02:40-16:06:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C26


2026/01/29(029)16:10:01-16:13:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0056-00 2026/01/29(029)16:15:00-16:18:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0106+01 2026/01/29(029)16:24:42-16:28:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0115-01 2026/01/29(029)16:34:05-16:37:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0128+03 2026/01/29(029)16:47:04-16:50:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C49


2026/01/29(029)16:57:00-17:00:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0155-109 2026/01/29(029)17:13:23-17:16:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0218-021 2026/01/29(029)17:36:34-17:40:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0237-233 2026/01/29(029)17:55:36-17:59:02JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0246-202 2026/01/29(029)18:04:29-18:07:55JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

