




TOYOKAWA 1614-172 2026/02/18(049)06:15:52-06:19:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1623-228 2026/02/18(049)06:25:12-06:28:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1631-222 2026/02/18(049)06:33:42-06:37:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1638-025 2026/02/18(049)06:39:19-06:42:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1644-106 2026/02/18(049)06:46:14-06:49:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1650+004 2026/02/18(049)06:51:34-06:55:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1656+053 2026/02/18(049)06:57:06-07:00:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2026/02/18(049)07:13:36-07:17:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1730-13 2026/02/18(049)07:31:38-07:35:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1748+031 2026/02/18(049)07:49:02-07:52:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1759+13 2026/02/18(049)07:59:55-08:03:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1819-096 2026/02/18(049)08:20:56-08:24:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1830-210 2026/02/18(049)08:32:12-08:35:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1853+028 2026/02/18(049)08:54:06-08:57:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1908-20 2026/02/18(049)09:09:21-09:12:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1915-121 2026/02/18(049)09:16:11-09:19:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1928-142 2026/02/18(049)09:29:53-09:33:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1938-15 2026/02/18(049)09:39:32-09:42:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2007+502 2026/02/18(049)10:06:43-10:10:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2014+358 2026/02/18(049)10:14:27-10:17:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C422

2026/02/18(049)10:45:05-10:48:31JST


13801+/- 3661




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2105-072 2026/02/18(049)11:05:42-11:09:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2131+379 2026/02/18(049)11:31:27-11:34:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2135-209 2026/02/18(049)11:35:46-11:39:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2147+145 2026/02/18(049)11:48:05-11:51:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2156-043 2026/02/18(049)11:57:10-12:00:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2203-18 2026/02/18(049)12:03:59-12:07:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2210+016 2026/02/18(049)12:10:21-12:13:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2218+395 2026/02/18(049)12:18:01-12:21:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C446

2026/02/18(049)12:23:31-12:26:57JST


11365+/- 383




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2229-093 2026/02/18(049)12:30:14-12:33:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2235+511 2026/02/18(049)12:34:46-12:38:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2239+333 2026/02/18(049)12:38:59-12:42:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2243+394 2026/02/18(049)12:43:16-12:46:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C454.3 2026/02/18(049)12:51:30-12:54:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2259+481 2026/02/18(049)12:59:12-13:02:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C456

2026/02/18(049)13:10:01-13:13:27JST

12652+/- 683




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C459

2026/02/18(049)13:14:06-13:17:32JST


10978+/- 397




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2318-16 2026/02/18(049)13:18:34-13:22:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2325+269 2026/02/18(049)13:25:26-13:28:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2344+09 2026/02/18(049)13:44:05-13:47:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2347-02 2026/02/18(049)13:47:51-13:51:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2354+14 2026/02/18(049)13:54:45-13:58:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C2

2026/02/18(049)14:03:47-14:07:13JST


13656+/- 7932




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0011+344 2026/02/18(049)14:11:09-14:14:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0019-00 2026/02/18(049)14:19:46-14:23:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C12

2026/02/18(049)14:30:00-14:33:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0038+328 2026/02/18(049)14:38:18-14:41:44JST


12159+/- 135




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0044-056 2026/02/18(049)14:44:02-14:47:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C26


2026/02/18(049)14:51:23-14:54:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0056-00 2026/02/18(049)14:56:22-14:59:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0106+01 2026/02/18(049)15:06:04-15:09:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0115-01 2026/02/18(049)15:15:27-15:18:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0120+405 2026/02/18(049)15:20:49-15:24:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C48


2026/02/18(049)15:35:01-15:38:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0148+274 2026/02/18(049)15:48:44-15:52:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0155-109 2026/02/18(049)15:54:45-15:58:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0202+15 2026/02/18(049)16:01:52-16:05:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0213+178 2026/02/18(049)16:13:43-16:17:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C67

2026/02/18(049)16:21:25-16:24:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C71


2026/02/18(049)16:39:40-16:43:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2026/02/18(049)16:58:56-17:02:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0308+305 2026/02/18(049)17:08:45-17:12:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA CTA21 2026/02/18(049)17:15:59-17:19:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0320+05 2026/02/18(049)17:20:16-17:23:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2026/02/18(049)17:24:21-17:27:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0332-187 2026/02/18(049)17:31:46-17:35:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0338-196 2026/02/18(049)17:37:47-17:41:13JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0349-092 2026/02/18(049)17:48:21-17:51:47JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

