




T20260426054319





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


2007+502 2026/04/25 20.75UT TOYOKAWA-FUJI



T20260426054319





BLK: 6,SNR1: 3.5794 ,SNR2: 6.5634




Frequency (Hz)

K20260426054316




BLK: 6,SNR1: 6.8726 ,SNR2: 16.827





Frequency (Hz)


2007+502 2026/04/25 20.75UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20260426054316




No.Good Data




Frequency (Hz)


2007+502 2026/04/25 20.75UT FUJI -KISO





T20260426060932




BLK: 7,SNR1: 21.450 ,SNR2: 51.635




F20260426060934




BLK: 7,SNR1: 2.8403 ,SNR2: 7.4493




2033+375 2026/04/25 21.19UT TOYOKAWA-FUJI



T20260426060932





BLK: 7,SNR1: 16.962 ,SNR2: 41.120





2033+375 2026/04/25 21.19UT TOYOKAWA-KISO



K20260426060930




BLK: 7,SNR1: 7.1065 ,SNR2: 17.510



F20260426060934





BLK: 7,SNR1: 0.42300 ,SNR2: 1.7974




Frequency (Hz)

K20260426060930




BLK: 7,SNR1: 1.2133 ,SNR2: 2.9080




Frequency (Hz)


2033+375 2026/04/25 21.19UT FUJI -KISO




T20260426061445




BLK: 3,SNR1: 1.7590 ,SNR2: 9.9772




F20260426061447





BLK: 3,SNR1: 8.6147 ,SNR2: 15.268




2038+363 2026/04/25 21.27UT TOYOKAWA-FUJI



T20260426061445





BLK: 1,SNR1: 1.2071 ,SNR2: 4.8273




Frequency (Hz)

K20260426061443




BLK: 1,SNR1: 8.1294 ,SNR2: 20.919





Frequency (Hz)


2038+363 2026/04/25 21.27UT TOYOKAWA-KISO



F20260426061447





BLK: 1, SNR1: 2.4656 , SNR2: 11.247




Frequency (Hz)

2038+363 2026/04/25 21.27UT FUJI -KISO


K20260426061443




BLK: 1, SNR1: 9.7647 , SNR2: 24.282




Frequency (Hz)





T20260426062551




BLK: 6,SNR1: 19.075 ,SNR2: 41.789




F20260426062553




BLK: 6,SNR1: 14.227 ,SNR2: 30.159




2049+166 2026/04/25 21.46UT TOYOKAWA-FUJI




T20260426062551




BLK: 2,SNR1: 23.559 ,SNR2: 55.140




K20260426062549





BLK: 2,SNR1: 20.210 ,SNR2: 35.818




2049+166 2026/04/25 21.46UT TOYOKAWA-KISO



F20260426062553





BLK: 3,SNR1: 6.4720 ,SNR2: 16.293




Frequency (Hz)

K20260426062549




BLK: 3,SNR1: 8.5388 ,SNR2: 21.032





Frequency (Hz)


2049+166 2026/04/25 21.46UT FUJI -KISO



T20260426063337




BLK: 4,SNR1: 39.064 ,SNR2: 169.03




Frequency (Hz)

F20260426063339




BLK: 4,SNR1: 0.50052E-01,SNR2: 1.6840





Frequency (Hz)


2056+028 2026/04/25 21.59UT TOYOKAWA-FUJI



T20260426063337





BLK: 6,SNR1: 51.965 ,SNR2: 206.70




Frequency (Hz)

K20260426063335




BLK: 6,SNR1: 3.4689 ,SNR2: 8.7292




Frequency (Hz)


2056+028 2026/04/25 21.59UT TOYOKAWA-KISO



F20260426063339





BLK: 1,SNR1:-0.82822E-01,SNR2: 0.68670




Frequency (Hz)

K20260426063335




BLK: 1,SNR1: 1.7680 ,SNR2: 7.8820





Frequency (Hz)


2056+028 2026/04/25 21.59UT FUJI -KISO



T20260426064219





BLK: 4,SNR1: 8.3863 ,SNR2: 20.973




Frequency (Hz)

F20260426064221




BLK: 4,SNR1: 2.6290 ,SNR2: 11.868





Frequency (Hz)


2105-072 2026/04/25 21.73UT TOYOKAWA-FUJI



T20260426064219





BLK: 5,SNR1: 1.2251 ,SNR2: 4.2462




Frequency (Hz)

K20260426064216




BLK: 5,SNR1: 7.6830 ,SNR2: 14.176




Frequency (Hz)


2105-072 2026/04/25 21.73UT TOYOKAWA-KISO





F20260426064221




BLK: 3,SNR1:-0.94830E-01,SNR2: 1.0507




K20260426064216





BLK: 3,SNR1: 0.10654 ,SNR2: 5.6764




2105-072 2026/04/25 21.73UT FUJI -KISO



T20260426065724





BLK: 2,SNR1: 85.614 ,SNR2: 543.17




Frequency (Hz)

F20260426065726




BLK: 2,SNR1: 2.3488 ,SNR2: 4.2397





Frequency (Hz)


2120-102 2026/04/25 21.98UT TOYOKAWA-FUJI



T20260426065724





BLK: 5, SNR1: 68.870 ,SNR2: 411.33




Frequency (Hz)

K20260426065721




BLK: 5, SNR1: 10.220 ,SNR2: 18.190





Frequency (Hz)


2120-102 2026/04/25 21.98UT TOYOKAWA-KISO





F20260426065726




BLK: 1,SNR1: 0.33890E-01,SNR2: 2.1102




K20260426065721





BLK: 1,SNR1: 0.32708E-01,SNR2: 0.79753




2120-102 2026/04/25 21.98UT FUJI -KISO



T20260426070803





BLK:15,SNR1: 1.8920 ,SNR2: 5.5721




Frequency (Hz)

F20260426070805




BLK:15,SNR1: 9.0454 ,SNR2: 14.205





Frequency (Hz)


2131+379 2026/04/25 22.16UT TOYOKAWA-FUJI



T20260426070803





BLK:13,SNR1: 1.6352 ,SNR2: 4.5460




Frequency (Hz)

K20260426070800




BLK:13,SNR1: 7.7070 ,SNR2: 19.985





Frequency (Hz)


2131+379 2026/04/25 22.16UT TOYOKAWA-KISO





F20260426070805




BLK:17,SNR1: 2.9447 ,SNR2: 9.0351




K20260426070800





BLK:17,SNR1: 7.6085 ,SNR2: 20.006




2131+379 2026/04/25 22.16UT FUJI -KISO



T20260426072442




BLK: 3,SNR1: 7.1820 ,SNR2: 18.394




Frequency (Hz)

F20260426072444




BLK: 3,SNR1: 6.1261 ,SNR2: 18.212





Frequency (Hz)


2147+145 2026/04/25 22.44UT TOYOKAWA-FUJI



T20260426072442





BLK: 9,SNR1: 8.7390 ,SNR2: 21.967




Frequency (Hz)

K20260426072439




BLK: 9,SNR1: 8.1477 ,SNR2: 24.450





Frequency (Hz)


2147+145 2026/04/25 22.44UT TOYOKAWA-KISO



F20260426072444





BLK: 5,SNR1: 6.5392 ,SNR2: 14.762




Frequency (Hz)

K20260426072439




BLK: 5,SNR1: 10.404 ,SNR2: 18.423





Frequency (Hz)


2147+145 2026/04/25 22.44UT FUJI -KISO



T20260426073347





BLK: 9,SNR1: 6.2236 ,SNR2: 23.464




Frequency (Hz)

F20260426073349




BLK: 9,SNR1: 2.0195 ,SNR2: 9.9517





Frequency (Hz)


2156-043 2026/04/25 22.59UT TOYOKAWA-FUJI



T20260426073347





BLK:11,SNR1: 10.703 ,SNR2: 25.000




Frequency (Hz)

K20260426073344




BLK:11,SNR1: 8.8725 ,SNR2: 21.837





Frequency (Hz)


2156-043 2026/04/25 22.59UT TOYOKAWA-KISO



F20260426073349





BLK:10,SNR1: 1.9444 ,SNR2: 9.6621




Frequency (Hz)

K20260426073344




BLK:10,SNR1: 9.0227 ,SNR2: 21.955





Frequency (Hz)


2156-043 2026/04/25 22.59UT FUJI -KISO



T20260426074035





BLK: 4,SNR1: 0.47246 ,SNR2: 3.6815




Frequency (Hz)

F20260426074037




BLK: 4,SNR1:-0.69903E-01,SNR2: 0.44233





Frequency (Hz)


2203-18 2026/04/25 22.70UT TOYOKAWA-FUJI



T20260426074035





BLK: 1,SNR1: 0.23984 ,SNR2: 5.6524




Frequency (Hz)

K20260426074032




BLK: 1,SNR1: 0.30529 ,SNR2: 3.2914




Frequency (Hz)


2203-18 2026/04/25 22.70UT TOYOKAWA-KISO



F20260426074037





BLK: 1,SNR1: 1.7469 ,SNR2: 8.3195




Frequency (Hz)

2203-18 2026/04/25 22.70UT FWJ -KISO


K20260426074032





BLK: 1,SNR1: 0.20261 ,SNR2: 3.1247




Frequency (Hz)





T20260426074657




No.Good Data




F20260426074659





No.Good Data




2210+016 2026/04/25 22.81UT TOYOKAWA-FUJI



T20260426074657





No.Good Data




Frequency (Hz)

K20260426074654




No.Good Data




Frequency (Hz)


2210+016 2026/04/25 22.81UT TOYOKAWA-KISO





F20260426074659




No.Good Data




K20260426074654




No.Good Data




2210+016 2026/04/25 22.81UT FUJI -KISO





T20260426075420




BLK: 5,SNR1: 0.68980E-01,SNR2: 0.45248




F20260426075422





BLK: 5,SNR1: 9.1182 ,SNR2: 62.716




2217+128 2026/04/25 22.93UT TOYOKAWA-FUJI





T20260426075420




BLK: 2,SNR1: 0.16735E-01,SNR2: 1.5909




K20260426075417





BLK: 2,SNR1: 0.74335 ,SNR2: 6.5904




2217+128 2026/04/25 22.93UT TOYOKAWA-KISO





F20260426075422




BLK: 1,SNR1: 0.19728 ,SNR2: 2.6281




K20260426075417





BLK: 1,SNR1: 1.0761 ,SNR2: 9.7458




2217+128 2026/04/25 22.93UT FUJI -KISO



T20260426080007





BLK: 2, SNR1: 13.042 , SNR2: 21.247




Frequency (Hz)

3C446 2026/04/25 23.03UT TOYOKAWA-FUJI


F20260426080009





BLK: 2, SNR1: 7.5367 , SNR2: 16.457




Frequency (Hz)



T20260426080007





BLK: 2,SNR1: 32.014 ,SNR2: 36.551




Frequency (Hz)

3C446 2026/04/25 23.03UT TOYOKAWA-KISO


K20260426080004





BLK: 2,SNR1: 18.055 ,SNR2: 35.496




Frequency (Hz)



F20260426080009





BLK: 3,SNR1: 12.007 ,SNR2: 19.939




Frequency (Hz)

3C446 2026/04/25 23.03UT FUJI -KISO


K20260426080004





BLK: 3,SNR1: 6.2987 ,SNR2: 15.962




Frequency (Hz)



T20260426080651





BLK: 6,SNR1: 20.958 ,SNR2: 43.134




Frequency (Hz)

2229-093 2026/04/25 23.14UT TOYOKAWA-FUJI


F20260426080653





BLK: 6,SNR1: 91.412 ,SNR2: 107.27




Frequency (Hz)



T20260426080651





BLK: 1,SNR1: 22.750 ,SNR2: 50.666




Frequency (Hz)

K20260426080648




BLK: 1,SNR1: 19.050 ,SNR2: 38.823





Frequency (Hz)


2229-093 2026/04/25 23.14UT TOYOKAWA-KISO



F20260426080653





BLK: 3,SNR1: 87.009 ,SNR2: 102.11




Frequency (Hz)

K20260426080648




BLK: 3,SNR1: 19.600 ,SNR2: 40.342




Frequency (Hz)


2229-093 2026/04/25 23.14UT FUJI -KISO





T20260426081518




BLK: 9,SNR1: 7.8434 ,SNR2: 20.132




F20260426081520





BLK: 9,SNR1: 1.0308 ,SNR2: 2.6160




2238-113 2026/04/25 23.28UT TOYOKAWA-FUJI



T20260426081518





BLK:10,SNR1: 4.5407 ,SNR2: 20.035




Frequency (Hz)

K20260426081515




BLK:10,SNR1: 7.6342 ,SNR2: 14.222




Frequency (Hz)


2238-113 2026/04/25 23.28UT TOYOKAWA-KISO




F20260426081520




BLK: 8,SNR1: 0.70862E-01,SNR2: 2.8737




K20260426081515




BLK: 8,SNR1: 8.2431 ,SNR2: 15.346




2238-113 2026/04/25 23.28UT FUJI -KISO



T20260426082807




BLK: 3,SNR1: 3.3801 ,SNR2: 8.6016





3C454.3 2026/04/25 23.50UT TOYOKAWA-FUJI


F20260426082809




BLK: 3,SNR1: 1.8081 ,SNR2: 6.2043



T20260426082807




BLK: 5,SNR1: 6.0093 ,SNR2: 13.692





3C454.3 2026/04/25 23.50UT TOYOKAWA-KISO


K20260426082804




BLK: 5,SNR1: 3.6737 ,SNR2: 8.1675



F20260426082809




BLK: 4,SNR1: 3.5559 ,SNR2: 10.574





3C454.3 2026/04/25 23.50UT FUJI -KISO



K20260426082804




BLK: 4,SNR1: 3.0343 ,SNR2: 9.2645





T20260426083549




BLK: 1, SNR1: 0.51072 , SNR2: 1.9251




F20260426083551





BLK: 1, SNR1: 10.051 , SNR2: 24.710




2259+481 2026/04/25 23.63UT TOYOKAWA-FUJI




T20260426083549




BLK: 4,SNR1:-0.73958E-01,SNR2: 1.3785




K20260426083546





BLK: 4,SNR1: 3.7678 ,SNR2: 10.968




2259+481 2026/04/25 23.63UT TOYOKAWA-KISO



F20260426083551




BLK: 1,SNR1:-0.24905 ,SNR2: 0.66728




Frequency (Hz)

K20260426083546




BLK: 1,SNR1:-0.23530 ,SNR2: 0.43391




Frequency (Hz)


2259+481 2026/04/25 23.63UT FUJI -KISO



T20260426085043





BLK: 6,SNR1: 4.4811 ,SNR2: 14.237





3C459 2026/04/25 23.87UT TOYOKAWA-FUJI



F20260426085045




BLK: 6,SNR1:-0.13510 ,SNR2: 1.1450



T20260426085043





BLK: 8,SNR1: 4.3645 ,SNR2: 16.126




Frequency (Hz)

3C459 2026/04/25 23.87UT TOYOKAWA-KISO


K20260426085040





BLK: 8,SNR1: 2.9860 ,SNR2: 12.574




Frequency (Hz)





F20260426085045




BLK: 1,SNR1: 0.30942E-01,SNR2: 2.1643




K20260426085040





BLK: 1,SNR1: 2.4409 ,SNR2: 4.6536




3C459 2026/04/25 23.87UT FUJI -KISO



T20260426090203




BLK: 4,SNR1: 11.137 ,SNR2: 27.600





2325+269 2026/04/26 0.06UT TOYOKAWA-FUJI



F20260426090205




BLK: 4,SNR1: 9.1579 ,SNR2: 22.602



T20260426090203





BLK: 3, SNR1: 7.6771 , SNR2: 19.163





2325+269 2026/04/26 0.06UT TOYOKAWA-KISO


K20260426090200




BLK: 3, SNR1: 8.3297 , SNR2: 20.637





F20260426090205




BLK: 2, SNR1: 1.3452 , SNR2: 3.9499




K20260426090200




BLK: 2, SNR1: 8.3975 , SNR2: 21.694




2325+269 2026/04/26 0.06UT FUJI -KISO



T20260426092428





BLK: 6, SNR1: 3.6611 ,SNR2: 9.0040





2347-02 2026/04/26 0.44UT TOYOKAWA-FUJI



F20260426092430




BLK: 6, SNR1: 0.69499 ,SNR2: 3.8238





T20260426092428




BLK: 3,SNR1: 9.7362 ,SNR2: 23.848




K20260426092425





BLK: 3,SNR1: 10.216 ,SNR2: 25.050




2347-02 2026/04/26 0.44UT TOYOKAWA-KISO



F20260426092430





BLK: 1,SNR1:-0.19634 ,SNR2: 2.3662





2347-02 2026/04/26 0.44UT FUJI -KISO


K20260426092425




BLK: 1,SNR1: 3.4995 ,SNR2: 10.916




T20260426093121




BLK:16,SNR1: 0.57130 ,SNR2: 2.8271




F20260426093123




BLK:16,SNR1: 11.354 ,SNR2: 26.621




2354+14 2026/04/26 0.55UT TOYOKAWA-FUJI



T20260426093121




BLK:21,SNR1: 2.4076 ,SNR2: 6.1882





2354+14 2026/04/26 0.55UT TOYOKAWA-KISO


K20260426093118




BLK:21,SNR1: 27.653 ,SNR2: 36.246




F20260426093123




BLK:28,SNR1: 17.732 ,SNR2: 31.518




K20260426093118





BLK:28,SNR1: 27.247 ,SNR2: 35.010




2354+14 2026/04/26 0.55UT FUJI -KISO



T20260426094024




BLK: 3,SNR1: 0.59315 ,SNR2: 3.2445





3C2 2026/04/26 0.70UT TOYOKAWA-FUJI



F20260426094026




BLK: 3,SNR1: 7.1087 ,SNR2: 17.059



T20260426094024




BLK: 3, SNR1: 1.1005 , SNR2: 3.8648





3C2 2026/04/26 0.70UT TOYOKAWA-KISO


K20260426094021




BLK: 3, SNR1: 8.4375 , SNR2: 20.817



F20260426094026




BLK: 2, SNR1: 2.4599 ,SNR2: 11.904





3C2 2026/04/26 0.70UT FUJI -KISO



K20260426094021




BLK: 2, SNR1: 9.4083 ,SNR2: 23.464




T20260426094746




BLK: 3,SNR1: 0.39591 ,SNR2: 0.99904




F20260426094748





BLK: 3,SNR1: 0.94454 ,SNR2: 2.1844




0011+344 2026/04/26 0.82UT TOYOKAWA-FUJI





T20260426094746




BLK: 5,SNR1: 0.40345 ,SNR2: 0.84267




K20260426094743




BLK: 5,SNR1: 2.4034 ,SNR2: 7.7478




0011+344 2026/04/26 0.82UT TOYOKAWA-KISO





F20260426094748




BLK: 5,SNR1: 0.76096 ,SNR2: 2.5731




K20260426094743




BLK: 5,SNR1: 1.8315 ,SNR2: 6.0140




0011+344 2026/04/26 0.82UT FUJI -KISO



T20260426095623





BLK: 4,SNR1: 3.2218 ,SNR2: 7.2353





0019-00 2026/04/26 0.97UT TOYOKAWA-FUJI


F20260426095625




BLK: 4,SNR1:-0.31325E-01,SNR2: 2.5234



T20260426095623





BLK: 7,SNR1: 0.75630 ,SNR2: 2.1269





0019-00 2026/04/26 0.97UT TOYOKAWA-KISO



K20260426095620




BLK: 7,SNR1: 8.6691 ,SNR2: 19.511





F20260426095625




BLK: 9, SNR1: 6.1500 ,SNR2: 14.239




K20260426095620





BLK: 9, SNR1: 4.3995 ,SNR2: 9.6223




0019-00 2026/04/26 0.97UT FUJI -KISO



T20260426100637




BLK:10,SNR1: 8.6665 ,SNR2: 24.304





3C12 2026/04/26 1.14UT TOYOKAWA-FUJI


F20260426100639




BLK:10,SNR1: 10.620 ,SNR2: 25.327



T20260426100637




BLK: 5,SNR1: 8.4603 ,SNR2: 24.076





3C12 2026/04/26 1.14UT TOYOKAWA-KISO


K20260426100634




BLK: 5,SNR1: 18.492 ,SNR2: 42.848



F20260426100639




BLK:10,SNR1: 10.963 ,SNR2: 26.005





3C12 2026/04/26 1.14UT FUJI -KISO


K20260426100634




BLK:10,SNR1: 16.369 ,SNR2: 38.380




T20260426102039




BLK:13,SNR1: 5.7044 ,SNR2: 14.817




F20260426102041




BLK:13,SNR1: 7.3380 ,SNR2: 17.902




0044-056 2026/04/26 1.37UT TOYOKAWA-FUJI





T20260426102039




BLK:16,SNR1: 8.4861 ,SNR2: 20.004




K20260426102036




BLK:16,SNR1: 8.0905 ,SNR2: 20.989




0044-056 2026/04/26 1.37UT TOYOKAWA-KISO





F20260426102041




BLK: 9, SNR1: 7.2412 ,SNR2: 18.512




K20260426102036




BLK: 9, SNR1: 8.3808 ,SNR2: 22.769




0044-056 2026/04/26 1.37UT FUJI -KISO



T20260426102800




BLK: 8,SNR1: 7.7193 ,SNR2: 19.620





3C26 2026/04/26 1.49UT TOYOKAWA-FUJI


F20260426102802




BLK: 8,SNR1: 11.031 ,SNR2: 26.647



T20260426102800




BLK: 7, SNR1: 6.2385 ,SNR2: 17.930





3C26 2026/04/26 1.49UT TOYOKAWA-KISO


K20260426102757




BLK: 7, SNR1: 12.213 ,SNR2: 30.711



F20260426102802




BLK: 8,SNR1: 11.218 ,SNR2: 26.324




3C26 2026/04/26 1.49UT FUJI -KISO


K20260426102757




BLK: 8,SNR1: 16.806 ,SNR2: 39.717




Frequency (Hz)




T20260426103258




BLK: 9,SNR1: 47.053 ,SNR2: 92.881




F20260426103300




BLK: 9,SNR1: 9.9564 ,SNR2: 27.008




0056-00 2026/04/26 1.58UT TOYOKAWA-FUJI




T20260426103258




BLK:13,SNR1: 38.762 ,SNR2: 65.612




K20260426103255




BLK:13,SNR1: 26.059 ,SNR2: 30.150




0056-00 2026/04/26 1.58UT TOYOKAWA-KISO




F20260426103300




BLK:13,SNR1: 8.3073 ,SNR2: 22.506




K20260426103255




BLK:13,SNR1: 23.404 ,SNR2: 30.512




0056-00 2026/04/26 1.58UT FUJI -KISO



T20260426104241





BLK: 4,SNR1: 9.8627 ,SNR2: 25.186




0106+01 2026/04/26 1.74UT TOYOKAWA-FUJI


F20260426104243




BLK: 4,SNR1: 10.568 ,SNR2: 25.751




Frequency (Hz)



T20260426104241





BLK: 2,SNR1: 10.477 ,SNR2: 26.790




0106+01 2026/04/26 1.74UT TOYOKAWA-KISO


K20260426104238





BLK: 2,SNR1: 6.0396 ,SNR2: 15.783




Frequency (Hz)





F20260426104243




BLK: 4,SNR1: 10.378 ,SNR2: 25.290




K20260426104238





BLK: 4,SNR1: 9.2637 ,SNR2: 23.901




0106+01 2026/04/26 1.74UT FUJI -KISO




T20260426105331




BLK:12,SNR1: 0.85238 ,SNR2: 3.8815




F20260426105333





BLK:12,SNR1: 3.5531 ,SNR2: 5.6263




0116+31 2026/04/26 1.92UT TOYOKAWA-FUJI



T20260426105331




BLK:18,SNR1: 0.76143 ,SNR2: 2.2456





0116+31 2026/04/26 1.92UT TOYOKAWA-KISO


K20260426105328




BLK:18,SNR1: 2.5187 ,SNR2: 10.044





F20260426105333




BLK: 9,SNR1: 0.37372E-01,SNR2: 1.4700




K20260426105328




BLK: 9,SNR1: 4.2421 ,SNR2: 16.533




0116+31 2026/04/26 1.92UT FUJI -KISO



T20260426110353




BLK: 8,SNR1: 8.0373 ,SNR2: 22.612





3C43 2026/04/26 2.09UT TOYOKAWA-FUJI


F20260426110355




BLK: 8,SNR1: 12.523 ,SNR2: 30.489





T20260426110353




BLK:10,SNR1: 7.6971 ,SNR2: 22.305




K20260426110350





BLK:10,SNR1: 8.8475 ,SNR2: 22.034




3C43 2026/04/26 2.09UT TOYOKAWA-KISO



F20260426110355





BLK: 5,SNR1: 8.6708 ,SNR2: 20.905




Frequency (Hz)

3C43 2026/04/26 2.09UT FUJI -KISO


K20260426110350




BLK: 5,SNR1: 8.5288 ,SNR2: 21.734




Frequency (Hz)





T20260426111137




BLK:14,SNR1: 11.813 ,SNR2: 27.713




F20260426111139




BLK:14,SNR1: 8.1935 ,SNR2: 20.224




3C48 2026/04/26 2.22UT TOYOKAWA-FUJI



T20260426111137





BLK:18,SNR1: 6.9211 ,SNR2: 20.019





3C48 2026/04/26 2.22UT TOYOKAWA-KISO



K20260426111135




BLK:18,SNR1: 9.2729 ,SNR2: 23.186



F20260426111139





BLK: 7,SNR1: 8.8441 ,SNR2: 22.096





3C48 2026/04/26 2.22UT FUJI -KISO


K20260426111135




BLK: 7,SNR1: 10.398 ,SNR2: 25.665




T20260426113121




BLK: 6,SNR1: 2.3423 ,SNR2: 13.670




F20260426113123




BLK: 6,SNR1: 1.3067 ,SNR2: 3.6035




0155-109 2026/04/26 2.55UT TOYOKAWA-FUJI




T20260426113121




BLK:15,SNR1: 2.9233 ,SNR2: 6.8113




K20260426113119




BLK:15,SNR1: 0.34269 ,SNR2: 1.8220




0155-109 2026/04/26 2.55UT TOYOKAWA-KISO




F20260426113123




BLK: 3,SNR1: 1.3830 ,SNR2: 4.0243




K20260426113119




BLK: 3,SNR1: 0.99056 ,SNR2: 4.0070




0155-109 2026/04/26 2.55UT FUJI -KISO




T20260426115019




BLK:30,SNR1: 60.005 ,SNR2: 100.72




F20260426115021




BLK:30,SNR1: 9.1514 ,SNR2: 21.979




0213+178 2026/04/26 2.87UT TOYOKAWA-FUJI




T20260426115019




BLK:25,SNR1: 58.431 ,SNR2: 136.39




K20260426115017




BLK:25,SNR1: 13.750 ,SNR2: 29.846




0213+178 2026/04/26 2.87UT TOYOKAWA-KISO




F20260426115021




BLK:25,SNR1: 10.179 ,SNR2: 22.617




K20260426115017




BLK:25,SNR1: 15.499 ,SNR2: 30.058




0213+178 2026/04/26 2.87UT FUJI -KISO




T20260426115802




BLK: 3,SNR1: 7.1674 ,SNR2: 12.756




F20260426115804






BLK: 3,SNR1: 17.485 ,SNR2: 30.867





3C67 2026/04/26 3.00UT TOYOKAWA-FUJI




T20260426115802





K20260426115759




3C67 2026/04/26 3.00UT TOYOKAWA-KISO





F20260426115804




No. Good Data




K20260426115759





No. Good Data




3067 2026/04/26 3.00UT FUJI -KISO





T20260426121616




BLK: 1,SNR1: 0.12417 ,SNR2: 0.76908




F20260426121618





BLK: 1,SNR1:-0.24144 ,SNR2: 0.0000




3C71 2026/04/26 3.30UT TOYOKAWA-FUJI





T20260426121616




BLK: 5,SNR1: 0.79754E-01,SNR2: 1.2969




K20260426121613





BLK: 5,SNR1: 2.9054 ,SNR2: 11.925




3C71 2026/04/26 3.30UT TOYOKAWA-KISO



F20260426121618





BLK: 2,SNR1: 0.51510 ,SNR2: 2.1413





3C71 2026/04/26 3.30UT FUJI -KISO



K20260426121613




BLK: 2,SNR1: 1.8348 ,SNR2: 9.1576





T20260426123532




BLK: 1,SNR1: 1.4766 ,SNR2: 4.4327




F20260426123534





BLK: 1,SNR1:-0.16123 ,SNR2: 1.6413




0258+350 2026/04/26 3.62UT TOYOKAWA-FUJI





T20260426123532




BLK: 6,SNR1: 3.0641 ,SNR2: 5.3026




K20260426123529





BLK: 6,SNR1: 0.84316 ,SNR2: 4.7790




0258+350 2026/04/26 3.62UT TOYOKAWA-KISO





F20260426123534




BLK: 7,SNR1:-0.23266E-01,SNR2: 1.8645




K20260426123529




BLK: 7,SNR1: 5.5204 ,SNR2: 11.923




0258+350 2026/04/26 3.62UT FUJI -KISO




T20260426124521




BLK:11,SNR1: 6.7619 ,SNR2: 12.035




F20260426124523




BLK:11,SNR1: 8.4078 ,SNR2: 20.522




0308+305 2026/04/26 3.78UT TOYOKAWA-FUJI




T20260426124521




BLK:10,SNR1: 4.9383 ,SNR2: 8.3582




K20260426124518




BLK:10,SNR1: 13.486 ,SNR2: 22.982




0308+305 2026/04/26 3.78UT TOYOKAWA-KISO




F20260426124523




BLK:10,SNR1: 12.413 ,SNR2: 22.890




K20260426124518




BLK:10,SNR1: 14.002 ,SNR2: 24.950




0308+305 2026/04/26 3.78UT FUJI -KISO




T20260426125652




BLK: 2,SNR1: 1.5691 ,SNR2: 4.0298




F20260426125654




BLK: 2,SNR1:-0.45385E-01,SNR2: 0.97663




0320+05 2026/04/26 3.98UT TOYOKAWA-FUJI





T20260426125652




BLK: 3,SNR1: 1.5926 ,SNR2: 6.9109




K20260426125649




BLK: 3,SNR1: 0.88607 ,SNR2: 4.4477




0320+05 2026/04/26 3.98UT TOYOKAWA-KISO





F20260426125654




BLK: 1,SNR1: -0.39397 ,SNR2: 0.53320




K20260426125649





BLK: 1,SNR1: 1.0663 ,SNR2: 5.9751




0320+05 2026/04/26 3.98UT FUJI -KISO





T20260426131014




BLK: 5,SNR1: 10.676 ,SNR2: 32.939




F20260426131016





BLK: 5,SNR1:-0.34649E-01,SNR2: 1.7206




0333+32 2026/04/26 4.20UT TOYOKAWA-FUJI




T20260426131014




BLK: 9,SNR1: 12.007 ,SNR2: 25.577




K20260426131011







BLK: 9,SNR1: 1.8674 ,SNR2: 5.6799




0333+32 2026/04/26 4.20UT TOYOKAWA-KISO








0333+32 2026/04/26 4.20UT FUJI -KISO





T20260426132315




BLK: 3,SNR1: 16.671 ,SNR2: 30.436




F20260426132317





BLK: 3,SNR1: 14.545 ,SNR2: 25.769




0347+05 2026/04/26 4.42UT TOYOKAWA-FUJI





T20260426132315




BLK: 8,SNR1: 7.8294 ,SNR2: 13.991




K20260426132312





BLK: 8,SNR1: 8.5764 ,SNR2: 15.348




0347+05 2026/04/26 4.42UT TOYOKAWA-KISO





F20260426132317




BLK: 8,SNR1: 16.580 ,SNR2: 29.803




K20260426132312





BLK: 8,SNR1: 13.383 ,SNR2: 23.672




0347+05 2026/04/26 4.42UT FUJI -KISO





T20260426133849




No.Good Data




F20260426133851





No.Good Data




0403-132 2026/04/26 4.68UT TOYOKAWA-FUJI



T20260426133849





No.Good Data




Frequency (Hz)

K20260426133846




No.Good Data





Frequency (Hz)


0403-132 2026/04/26 4.68UT TOYOKAWA-KISO





F20260426133851




No.Good Data




K20260426133846




No.Good Data




0403-132 2026/04/26 4.68UT FUJI -KISO





T20260426134800




BLK: 1,SNR1: 0.53659E-01,SNR2: 1.3865




F20260426134802




BLK: 1,SNR1: 1.9693 ,SNR2: 7.0018





0411+05 2026/04/26 4.83UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.16035E-01,SNR2: 3.3572





BLK: 1,SNR1: 4.6959 ,SNR2: 10.718




0411+05 2026/04/26 4.83UT TOYOKAWA-KISO




F20260426134802




BLK: 1,SNR1: 17.447 ,SNR2: 30.843




K20260426134757





BLK: 1,SNR1: 8.5013 ,SNR2: 20.553




0411+05 2026/04/26 4.83UT FUJI -KISO




T20260426135854




BLK:16,SNR1: 2.2156 ,SNR2: 10.863




F20260426135856





BLK:16,SNR1: 1.5303 ,SNR2: 6.2594




0422+178 2026/04/26 5.01UT TOYOKAWA-FUJI





T20260426135854




BLK:14,SNR1: 1.6985 ,SNR2: 6.1578




K20260426135851




BLK:14,SNR1: 2.0706 ,SNR2: 7.8097




0422+178 2026/04/26 5.01UT TOYOKAWA-KISO




F20260426135856




BLK:12,SNR1: 1.2151 ,SNR2: 4.9471




K20260426135851





BLK:12,SNR1: 4.6434 ,SNR2: 9.3741




0422+178 2026/04/26 5.01UT FUJI -KISO





T20260426140629




No.Good Data




F20260426140631





No.Good Data




3C120 2026/04/26 5.14UT TOYOKAWA-FUJI



T20260426140629





No.Good Data




Frequency (Hz)

K20260426140626




No.Good Data




Frequency (Hz)


3C120 2026/04/26 5.14UT TOYOKAWA-KISO





F20260426140631




No.Good Data




K20260426140626





No.Good Data




3C120 2026/04/26 5.14UT FUJI -KISO




T20260426145430




BLK: 9,SNR1: 0.62038 ,SNR2: 3.2606




F20260426145432





BLK: 9,SNR1: 2.5196 ,SNR2: 6.1882




3C138 2026/04/26 5.94UT TOYOKAWA-FUJI





T20260426145430




BLK:12,SNR1: 0.52512 ,SNR2: 2.7593




K20260426145427





BLK:12,SNR1: 1.5193 ,SNR2: 2.2669




3C138 2026/04/26 5.94UT TOYOKAWA-KISO



F20260426145432





BLK: 7,SNR1: 4.6492 ,SNR2: 13.372




Frequency (Hz)

K20260426145427




BLK: 7,SNR1: 2.0793 ,SNR2: 3.1138





Frequency (Hz)


3C138 2026/04/26 5.94UT FUJI -KISO



T20260426150803




BLK: 9,SNR1: 2.2166 ,SNR2: 10.166




Frequency (Hz)

F20260426150805




BLK: 9,SNR1: 0.10709 ,SNR2: 2.7256





Frequency (Hz)


0531+194 2026/04/26 6.16UT TOYOKAWA-FUJI





T20260426150803




BLK:15,SNR1: 0.99961 ,SNR2: 2.6390




K20260426150800




BLK:15,SNR1: 0.84228 ,SNR2: 3.7383




0531+194 2026/04/26 6.16UT TOYOKAWA-KISO





F20260426150805




BLK:16,SNR1: 0.69347E-01,SNR2: 1.9785




K20260426150800





BLK:16,SNR1: 2.7577 ,SNR2: 7.0358




0531+194 2026/04/26 6.16UT FUJI -KISO



T20260426151624





BLK: 2,SNR1: 6.1123 ,SNR2: 29.541




Frequency (Hz)

F20260426151626




BLK: 2,SNR1: 15.323 ,SNR2: 27.416





Frequency (Hz)


3C147 2026/04/26 6.30UT TOYOKAWA-FUJI



T20260426151624





BLK: 2,SNR1: 15.934 ,SNR2: 28.048




Frequency (Hz)

K20260426151621




BLK: 2,SNR1: 10.928 ,SNR2: 27.148





Frequency (Hz)


3C147 2026/04/26 6.30UT TOYOKAWA-KISO





F20260426151626




BLK: 4,SNR1: 15.755 ,SNR2: 27.306




K20260426151621





BLK: 4,SNR1: 18.227 ,SNR2: 32.333




3C147 2026/04/26 6.30UT FUJI -KISO





T20260426152434




BLK:13,SNR1: 0.90635 ,SNR2: 4.3600




F20260426152436





BLK:13,SNR1: 5.9472 ,SNR2: 20.254




0548+16 2026/04/26 6.44UT TOYOKAWA-FUJI




T20260426152434




BLK: 6,SNR1: 1.6906 ,SNR2: 5.4650




K20260426152431





BLK: 6,SNR1: 16.113 ,SNR2: 24.453




0548+16 2026/04/26 6.44UT TOYOKAWA-KISO





F20260426152436




BLK: 7,SNR1: 21.324 ,SNR2: 29.889




K20260426152431




BLK: 7,SNR1: 18.160 ,SNR2: 26.722




0548+16 2026/04/26 6.44UT FUJI -KISO



T20260426152844





BLK:17,SNR1: 42.235 ,SNR2: 80.957




Frequency (Hz)

F20260426152846




BLK:17,SNR1: 8.6365 ,SNR2: 26.646




Frequency (Hz)


0552+12 2026/04/26 6.51UT TOYOKAWA-FUJI



T20260426152844





BLK:15,SNR1: 35.888 ,SNR2: 66.956




Frequency (Hz)

K20260426152841




BLK:15,SNR1: 11.136 ,SNR2: 25.677





Frequency (Hz)


0552+12 2026/04/26 6.51UT TOYOKAWA-KISO





F20260426152846




BLK:11,SNR1: 10.988 ,SNR2: 26.712




K20260426152841





BLK:11,SNR1: 11.474 ,SNR2: 26.458




0552+12 2026/04/26 6.51UT FUJI -KISO




T20260426153312




BLK: 7,SNR1: 2.0053 ,SNR2: 4.6159




F20260426153314




BLK: 7,SNR1: 1.2424 ,SNR2: 5.2773




0556+191 2026/04/26 6.58UT TOYOKAWA-FUJI





T20260426153312




BLK: 6,SNR1: 8.8999 ,SNR2: 25.249




K20260426153309




BLK: 6,SNR1: 13.140 ,SNR2: 24.377




0556+191 2026/04/26 6.58UT TOYOKAWA-KISO



F20260426153314




BLK: 3,SNR1: 2.7272 ,SNR2: 7.5229




Frequency (Hz)

K20260426153309




BLK: 3,SNR1: 10.516 ,SNR2: 24.620




Frequency (Hz)


0556+191 2026/04/26 6.58UT FUJI -KISO



T20260426153744




BLK: 2,SNR1: 18.007 ,SNR2: 31.073




Frequency (Hz)

F20260426153746




BLK: 2,SNR1: 11.392 ,SNR2: 27.178




Frequency (Hz)


3C152 2026/04/26 6.66UT TOYOKAWA-FUJI




T20260426153744




BLK: 1,SNR1: 7.0622 ,SNR2: 20.018




K20260426153741




BLK: 1,SNR1: 10.471 ,SNR2: 25.679




3C152 2026/04/26 6.66UT TOYOKAWA-KISO



F20260426153746




BLK: 3,SNR1: 20.033 ,SNR2: 36.859




Frequency (Hz)

K20260426153741




BLK: 3,SNR1: 10.492 ,SNR2: 25.730





Frequency (Hz)


3C152 2026/04/26 6.66UT FUJI -KISO



T20260426160004





BLK:13,SNR1: 2.6150 ,SNR2: 6.4378




Frequency (Hz)

F20260426160006




BLK:13,SNR1: 8.5287 ,SNR2: 15.284





Frequency (Hz)


3C161 2026/04/26 7.03UT TOYOKAWA-FUJI



T20260426160004





BLK:15,SNR1: 2.4157 ,SNR2: 6.1928




Frequency (Hz)

K20260426160001




BLK:15,SNR1: 6.2743 ,SNR2: 16.241





Frequency (Hz)


3C161 2026/04/26 7.03UT TOYOKAWA-KISO



F20260426160006





BLK:10,SNR1: 6.7210 ,SNR2: 17.326




Frequency (Hz)

K20260426160001




BLK:10,SNR1: 0.13158 ,SNR2: 3.7086




Frequency (Hz)


3C161 2026/04/26 7.03UT FUJI -KISO



T20260426162737




BLK: 1, SNR1: 8.9194 , SNR2: 22.052




Frequency (Hz)

F20260426162739




BLK: 1, SNR1: 3.6044 , SNR2: 30.797




Frequency (Hz)


0652-130 2026/04/26 7.49UT TOYOKAWA-FUJI





T20260426162737




No.Good Data




K20260426162734




No.Good Data




0652-130 2026/04/26 7.49UT TOYOKAWA-KISO



F20260426162739




BLK: 1, SNR1: 18.261 , SNR2: 44.177




Frequency (Hz)

K20260426162734




BLK: 1, SNR1: 2.6959 , SNR2: 12.201




Frequency (Hz)


0652-130 2026/04/26 7.49UT FUJI -KISO



T20260426163914




BLK: 4, SNR1: 3.6858 , SNR2: 10.543




Frequency (Hz)

F20260426163916




BLK: 4, SNR1: 6.5950 , SNR2: 17.190




Frequency (Hz)


0703+138 2026/04/26 7.68UT TOYOKAWA-FUJI



T20260426163914




BLK: 3,SNR1: 1.2493 ,SNR2: 3.8246




Frequency (Hz)

K20260426163911





BLK: 3,SNR1: 10.968 ,SNR2: 31.308





Frequency (Hz)

0703+138 2026/04/26 7.68UT TOYOKAWA-KISO







BLK: 5, SNR1: 7.7718 , SNR2: 19.747





BLK: 5, SNR1: 10.736 , SNR2: 30.567




0703+138 2026/04/26 7.68UT FUJI -KISO



T20260426164837




BLK: 3,SNR1: 0.50944E-01,SNR2: 0.97088




Frequency (Hz)

F20260426164839




BLK: 3,SNR1:-0.75564E-01,SNR2: 3.1048





Frequency (Hz)


0713-024 2026/04/26 7.84UT TOYOKAWA-FUJI



T20260426164837





BLK: 5,SNR1:-0.10425 ,SNR2: 0.27710




Frequency (Hz)

K20260426164834








BLK: 5,SNR1: 1.0179 ,SNR2: 3.0674




Frequency (Hz)

0713-024 2026/04/26 7.84UT TOYOKAWA-KISO








0713-024 2026/04/26 7.84UT FUJI -KISO



T20260426165849




BLK: 1,SNR1: 1.3349 ,SNR2: 13.898




Frequency (Hz)

F20260426165851




BLK: 1,SNR1: 0.20252 ,SNR2: 2.1050





Frequency (Hz)


0723+10 2026/04/26 8.01UT TOYOKAWA-FUJI



T20260426165849




No.Good Data




Frequency (Hz)

K20260426165846




No.Good Data





Frequency (Hz)


0723+10 2026/04/26 8.01UT TOYOKAWA-KISO



F20260426165851





No.Good Data




Frequency (Hz)

K20260426165846




No.Good Data




Frequency (Hz)


0723+10 2026/04/26 8.01UT FWJ -KISO



T20260426170904





BLK: 8,SNR1: 6.0884 ,SNR2: 14.583




Frequency (Hz)

F20260426170906




BLK: 8,SNR1: 10.382 ,SNR2: 18.591




Frequency (Hz)


0732+33 2026/04/26 8.18UT TOYOKAWA-FUJI



T20260426170904





BLK: 5,SNR1: 9.7278 ,SNR2: 23.118




Frequency (Hz)

K20260426170901




BLK: 5,SNR1: 9.9814 ,SNR2: 25.217





Frequency (Hz)


0732+33 2026/04/26 8.18UT TOYOKAWA-KISO



F20260426170906





BLK: 2,SNR1: 19.133 ,SNR2: 35.580




Frequency (Hz)

K20260426170901




BLK: 2,SNR1: 10.997 ,SNR2: 27.310




Frequency (Hz)


0732+33 2026/04/26 8.18UT FUJI -KISO



T20260426174651





BLK: 1,SNR1: 11.595 ,SNR2: 29.152




Frequency (Hz)

F20260426174653




BLK: 1,SNR1: 7.6052 ,SNR2: 20.039




Frequency (Hz)


3C196 2026/04/26 8.81UT TOYOKAWA-FUJI



T20260426174651




BLK: 6,SNR1: 7.0299 ,SNR2: 18.918




Frequency (Hz)

3C196 2026/04/26 8.81UT TOYOKAWA-KISO


K20260426174648




BLK: 6,SNR1: 9.3990 ,SNR2: 23.992




Frequency (Hz)



F20260426174653




BLK: 5,SNR1: 7.0441 ,SNR2: 19.815




Frequency (Hz)

K20260426174648



BLK: 5,SNR1: 9.5390 ,SNR2: 23.911



Frequency (Hz)

3C196 2026/04/26 8.81UT FUJI -KISO

